


PPPL	PRINCETON PLASMA PHYSICS LABORATORY ES&H DIRECTIVES		
	ES&HD 5008 SECTION 2, CHAPTER 1 Introduction		
Approved	Date: 03/14/08	Revision 6	Page 1 of 1

CHAPTER 1 INTRODUCTION

1.1 SCOPE

This Section 2.0 covers regulations, practices, and procedures set forth by PPPL to control and minimize the hazards associated with electrical systems and equipment.

1.2 APPLICATIONS

This Section 2.0 applies to all personnel directly engaged in work processes performed on electrical systems and equipment at the Laboratory during the life cycle of its facilities and projects. The administrative responsibilities, general safety practices, and procedures used to minimize hazards to personnel are in Chapter 2 through Chapter 5. Chapter 6 through Chapter 15 describe means used to mitigate the identified hazards associated with specific types of electrical equipment. Material in the References in Chapter 16 includes upper-tier requirements documents and/or recommended practices used to mitigate the consequences of electrical hazards. The Appendices of Chapter 17 depict methods used successfully to satisfy Section 2.0 requirements.